# ECHNICAL INFORMATION



P 1/8



Description ► Cordless Impact Driver

# CONCEPT AND MAIN APPLICATIONS

Models MT690/ MT691 are the first 14.4V/18V maktec cordless impact drivers powered by 1.1Ah Li-ion batteries L1451/ L1851 designed to provide the cost advantage.

These products are available in the following variations.

### MT690

	1/11 0/0						
	Model No.	Charger	Battery		Battery	Plastic	
			Type	Quantity	cover	carrying case	
	MT690Z	No	No	No	No	No	
	MT690E	DC1851	L1451	2	1	Yes	

# L Threshtony

The image above is MT691.

Dimensions: mm (")				
Length (L)	173 (6-13/16)			
Width (W)	82 (3-1/4)			
Height (H)	225 (8-7/8)			

### **MT691**

Madal Na	Charger	Battery		Battery	Plastic	Phillips	Haal
Model No.		Type	Quantity	cover	carrying case	bit 2-65	Hook
MT691Z	No	No	No	No	No	No	No
MT691E	DC1851	L1851	2	1	Yes	No*1	No*1

\*1: Yes for Taiwan

# ► Specification

Specificati	on Model	MT690	MT691	
	Voltage: V	14.4	18	
	Capacity: Ah	1.1		
Battery	Cell	Li-	ion	
	Energy capacity: Wh	1.6	20	
	Charging time: min.	60 with	DC1851	
Max outpu	it: W	23	30	
No load sp	peed: min1=rpm	0 - 2	,400	
Impacts pe	er minute: min1=ipm	0 - 3,000		
Driving sh		6.35mm (1/4") Hex		
Max. faster	ning torque*1: N.m [ kgf.cm] (in.lbs)	1: N.m [ kgf.cm] (in.lbs)   130 [1,330] (1,150)   135 [1,380] (		
	Machine screw	M4 - M8 (5/32" - 5/16")		
Capacities	Standard bolt	M5 - M14 (3	/16" - 9/16")	
Capacities	High tensile bolt	M5 - M12 (.	3/16" - 1/2")	
	Coarse thread (length)	22mm - 125mm	n (7/8" - 4-7/8")	
Electric br	ake	Y	es	
Torque adj	justment	No		
Variable s	peed control	Yes		
Reversing	function	Yes		
LED Job 1	ight	Yes No		
Weight acco	ording to edure 01/2003*2: kg (lbs)	1.4 (3.1) 1.5 (3.2)		

<sup>\*1:</sup> Torque at 3 seconds after seating, when fastening M14 high tensile bolt

# ► Standard equipment

See the model variation list above.

Note: The standard equipment for the tools may vary by country.

# ► Optional accessories

Charger DC1851 Li-ion battery L1451 (for MT690 only) Li-ion battery L1851 (for MT691 only)

<sup>\*2:</sup> MT690/with battery L1451, MT691/with battery L1851

CAUTION: Repair the machine in accordance with "Instruction manual" or "Safety instructions".


# [1] NECESSARY REPAIRING TOOLS

Code No.	Description	Use for
1R045	Gear extractor (large)	disassembling/ assembling Hammer section
1R232	Pipe 30	holding Anvil when disassembling Bit holder section
1R288	Screwdriver magnetizer	magnetizing a screwdriver for easy removal of steel balls
1R291 Retaining ring S and R pliers		removing Ring spring 11 of Bit holder section

### [2] LUBRICATION

Apply **Makita grease N. No.2** to the following portions designated with the black triangle to protect parts and product from unusual abrasion.

Item No.	Description	Portion to lubricate	Amount
	A	(a) Drum portion that contacts Sleeve 14 and Oil seal 14 of Hammer case	
16)	Anvil	(b) Hole portion into which (24) Spindle is inserted	a little
18)	Steel ball 3.5 (24 pcs.)	Surface that contacts 24 pcs. of Steel ball 3.5	a nece
22)	Steel ball 5.6 (2 pcs.)	Whole portion	
24)	Spindle	Hole portion into which DC motor's pinion gear is inserted	approx. 2 g




### [3] DISASSEMBLY/ASSEMBLY

### [3] -1. DC Motor

### DISASSEMBLING

(1) Disassemble DC motor as drawn in Fig. 2.


Fig. 2



### ASSEMBLING


(1) Assemble DC motor and Internal gear case as drawn in Fig. 3.

Fig. 3



(2) Before mounting Housing R to Housing L, assemble F/R change lever to Switch as drawn in Fig. 4.

Fig. 4



- [3] DISASSEMBLY/ASSEMBLY
- [3] -2. Anvil, Bit Holder Section

### DISASSEMBLING

- (1) Remove Hammer case and Hammer section from Housing set as per the left drawing in Fig. 2.
- (2) Disassemble Bit holder section and Anvil as drawn in Figs. 5 and 6.

Fig. 5





Fig. 6



### ASSEMBLING

Assemble Anvil and Bit holder section by reversing the disassembly procedure. (Figs. 6 and 5)


### [3] DISASSEMBLY/ASSEMBLY

### [3] -3. Hammer Section

### DISASSEMBLING

- (1) Remove Hammer case and Hammer section from Housing set as per the left drawing in Fig. 2.
- (2) Disassemble Hammer section as drawn in Figs. 7, 8, 9 and 10.

Fig. 7 Fig. 8



Hold Hammer section as shown below in Fig. R, and then release it from 1R045.

Caution:

Do not hold 1R045 as shown below in Fig. F when releasing Hammer section from 1R045.

Failure to follow this instruction could cause Steel balls to fall out of Hammer.

Fig. R

Fig. F

Fig. 9





Fig. 10




### [3] DISASSEMBLY/ASSEMBLY

## [3] -3. Hammer Section (cont.)

### **ASSEMBLING**


Assemble Hammer section by reversing the disassembly procedure. Refer to **Figs. 11, 10, 9** and **8**. Before putting Flat washer 24 in Hammer (Refer to **Fig. 10**), make sure that twenty-four Steel balls 3.5 are put in the groove of Hammer as shown in **Fig. 11**.

Fig. 11




# ► Circuit diagram

Fig. D-1



# ► Wiring diagram

Fig. D-2



Wiring to DC motor

Connect Lead wire (red) receptacle to the terminal with Red dot mark and Lead wire (black) receptacle to the other terminal.

Fig. D-3




Fig. D-4

